


INON

Compact Tripod UWTP-C1

Package, Name of Parts



Fastening Tripod Screw




Insert the provided 3/16" Allen wrench into the elevator tube.




Fit the wrench to the hex cap screw inside the tube and tighten clockwise.

Installing Options

- UW 3-Way Panhead
- Quick Shoe Ballhead UWTP-QB1
- Ballhead UWTP-B1
- M6 Ballhead UWTP-M6B1
- Ball 1/4-20UNC Adapter



Keep the two **M2 Cap Bolts** attached




Align the groove of the optional product with the **M2 Cap Bolt**, then tighten the tripod screw.

- GP 1/4-20UNC Adapter II




Remove the **M2 Cap Bolt** using the provided **1.5 mm Allen wrench**



Align the groove of the optional product with the **M2 Cap Bolt**, then tighten the tripod screw.

- Direct Base YS II




Remove both **M2 Cap Bolts**



Attach **Direct Base YS II** with supplied M5 screws.

- "Mount Adapter" supplied with ZD/SD Front Mask
- Single Light Holder·LE/LF for Tripod
- Tripod adapter
- Camera housing with a 1/4-inch 20UNC threaded hole (depth 5mm or more)





Remove both **M2 Cap Bolts**



The tripod screw alone secures without anti-loosen feature. Beware it may loosen from sudden shocks.

Using Elevator



Loosen the large dial to adjust the elevator column height.

Leg Length Adjustment



Open the lock lever



The legs can be extended by approximately 30 mm/1.2 inch.

Maintenance

- After use, rinse with fresh water to remove salt and dirt. Then dry thoroughly in a well-ventilated, shaded area out of direct sunlight.
- DO NOT** expose the product to fire or high heat sources, as this may cause deformation or damage.
- DO NOT** use organic solvents such as alcohol, benzene, or thinner, or any rust inhibitors, lubricants, polish, or detergents (especially alkaline ones) during cleaning. Some components of this product may deteriorate, become brittle, or dissolve upon contact with such substances.
- To prevent corrosion due to electrolysis, apply grease regularly to all metal screw threads.

Storage

- After drying, store the product in a dry, well-ventilated place out of direct sunlight.
- Avoid storage in environments with chemicals (such as camphor or mothballs), or in cold, hot, or humid conditions, or areas with drastic temperature changes, as these may cause deformation, damage, mold, rust, or corrosion.
- Keep out of reach of children. Small parts and accessories may pose a choking hazard if swallowed. In case of accidental ingestion, consult a doctor immediately.

Specifications

Weight	Air: 232 g/8.2 oz u/w: Approx102 g/3.6 oz
--------	--

Max height	Folded height	Lowest working height
230.5 mm/9.1 inch	154.5 mm/6.1 inch	101.5 mm/4.0 inch

INON INC.

2-18-9 Dai, Kamakura Kanagawa 247-0061 JAPAN

E-mail support@inon.co.jp URL <http://www.inon.jp/>

July 2025